

Grove

YB5515-2

322121

*Boom lift cylinder rust pitting bad on the chrome causing hyd leak. Cylinder need rebuild and re-chromed

*Mirrors need bolted back on chassis

*Hyd leak from hyd hoses for left front steer cylinder (small leak)

*No start code from ECU, power control, data interrupted, fuel rail pressure, cylinder miss fire.

*Will not turn over with key and is very hard to turn motor over. Due to the motor oil coming out the exhaust there is either internal problems with motor or turbo has came apart. Was not able to dig deeper into issues seeing cant get into motor bay for counter weights in the way for cover.